

Manganese Verona Pump Station

Test Results

Date Sample Collected	Sample Location	mg/L
5/31/2018	Plant Tap	Non-Detect
6/15/2018	Well Tap #13	0.56
6/15/2018	Well Tap #14	0.071
6/15/2018	Well Tap #15	0.023
6/15/2018	Well Tap #17	0.092
6/15/2018	Well Tap #36	0.31
6/15/2018	Well Tap #37	0.23
6/15/2018	Well Tap #38	0.28
6/15/2018	Well Tap #39	Non-Detect
6/15/2018	Well Tap #40	0.038
6/15/2018	Well Tap #41	0.15
6/15/2018	Well Tap #42	0.30
6/15/2018	Well Tap #43	0.31
6/15/2018	Well Tap #44	0.15
6/15/2018	Well Tap #45	0.061
6/15/2018	Well Tap #46	0.17
6/15/2018	Well Tap #47	0.13
6/15/2018	Well Tap #48	0.17
6/15/2018	Well Tap #49	0.12
6/15/2018	Well Tap #50	0.28
6/15/2018	Well Tap #51	0.077
6/15/2018	Well Tap #53	0.058
6/15/2018	Well Tap #54	0.07
6/20/2018	Raw Confluence Tap	0.12
6/20/2018	Plant Tap	Non-Detect
6/22/2018	Raw Confluence Tap	0.13
6/22/2018	Plant Tap	Non-Detect
6/23/2018	Raw Confluence Tap	0.14
6/23/2018	Plant Tap	Non-Detect
6/24/2018	Raw Confluence Tap	0.14
6/24/2018	Plant Tap	Non-Detect
6/25/2018	Raw Confluence Tap	0.15
6/25/2018	Plant Tap	Non-Detect
6/26/2018	Raw Confluence Tap	0.14
6/26/2018	Plant Tap	Non-Detect